

	CE Road Segment	Board-Endorsed Network	Rationale
1A	State Route 94 Segment: Boundary with Jamul to State Route 188 Existing Condition: 2 lanes Current Classification: Major Road (4+ lanes)	Draft Land Use Map: Downgrade Classification 2.1D Community Collector with Improvement Options (2+ lanes) Land Use Modification: The staff recommendation includes changes to the Tecate land use map.	 Road Capacity – Land use changes were needed in Tecate to reduce traffic volumes on State Route 94 to an acceptable LOS. Minimize Costs – See Key Issues. Minimize Environmental Impacts – State Route 94 passes through a number of wildlife preserves containing sensitive species and habitats. Additionally, visual impacts would be significant. Build Community Consensus – The Policy Advisory Committee recommended that CALTRANS plan State Route 94 as a two-lane road¹. Note: Proposed land use changes reduced ADTs along State Route 94 by 7K.
		Board Alternative Map: Equivalent Classification 4.1B Major Road with Intermittent Turn Lane (4+ lanes)	Road Capacity – A four-lane road will accommodate forecast traffic volumes at a level of service D or better.

Matrix: Mountain Empire-1 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
1B	State Route 94	Draft Land Use Map:	See comments for 1A.
	Segment: State Route 188 to Buckman	Downgrade Classification	
	Springs Road	2.1D Community Collector with	
	Existing Condition: 2 lanes	Improvement Options (2+ lanes)	
	<u>Current Classification</u> : Major Road (4+ lanes)		
		Land Use Modification:	
		The staff recommendation includes changes to the Tecate Draft Land Use Map.	
		Board Alternative Map: Minor Downgrade	Road Capacity - A four lane classification is needed to produce an acceptable level of
		4.1B Major Road with Intermittent Turn Lanes (Only to Harris Ranch Road)	service
1C	State Route 94	Downgrade Classification	• Road Capacity – This road segment will
	Segment: Buckman Springs Road to intersection with Old Hwy 80	2.1D Community Collector with Improvement Options (2+ lanes)	operate at an acceptable level of service with the proposed classification.
	Existing Condition: 2 lanes		
	Current Classification: Major Road (4+ lanes)		

Matrix: Mountain Empire-2 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
2	State Route 188 Segment: Entire Segment Existing Condition: 2 lanes Current Classification: Major Road (4+ lanes)	Draft Land Use Map: Equivalent Classification 4.1A Major Road with Raised Median (4+ lanes)	Road Capacity - Land use changes were needed in Tecate to improve LOS on State Route 94 from F to D. Note: Proposed Improvements are not identified in the SANDAG 2030 RTP
		Land Use Modification: Includes changes to the Tecate Draft Land Use Map.	
		Board Alternative Map: Upgrade Classification 6.2 Prime Arterial (6 lanes)	Road Capacity - A six lane road classification is needed to produce an acceptable level of service
3A	Potrero Valley / Harris Ranch Road (SC 680) Segment: .75 mile from State Route 94 to Potrero Park Road Existing Condition: 2 lanes Current Classification: Rural Light Collector Road (2 lanes)	Minor Downgrade 2.3C – Minor Collector (2 lanes)	 Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification. Build Community consensus – The Community desires bike lanes, sidewalks and curbs & gutter included with the standard for this segment of roadway located within the Village.
3B	Potrero Valley / Harris Ranch Road (SC 680) Segment: Potrero Park Road to SR-94 Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.

Matrix: Mountain Empire-3 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
4	Remaining Paved Road in Potrero Segment: Entire Segments Existing Condition: 2 lane roads Current Classification: Non- CE Roads	Existing Classification Map as Local Public Roads (2 lanes)	Road Capacity – Forecast traffic volumes are not sufficient to designate as a CE classification, nor do they meet the intent of CE Roads (to carry through traffic, goods and services). Also, dead end CE roads are discouraged
5A	Buckman Springs Road (SF 1403) Segment: Village Area, State Route 94 to southern boundary with Campo Tribal Land Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2C Light Collector with Intermittent Turn Lane (2+ lanes)	 Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification. Appropriate Road for Land Use – This classification selected to support town center planning effort
5B	Buckman Springs Road (SF 1403) Segment: Pine Valley Boundary to southern boundary with Campo Tribal Land Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes)	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.
6A	Old Hwy 80 (SC 1883) Segment: Pine Valley Boundary to intersection with State Route 94 Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2E Light Collector (2 lanes)	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.

Matrix: Mountain Empire-4 November 7, 2006

l	CE Road Segment	Board-Endorsed Network	Rationale
6B	Old Hwy 80 (SC 1883) Segment: Interstate 8 to Williams Road Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) at casino	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.
6C	Old Hwy 80 (SC 1883) Segment: State Route 94 to Ribbonwood Road Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) to east side of CPA boundary	Downgrade Classification 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes)	 Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification. Community Consensus – The community would like to retain the existing two- lane road with turn lane.
6D	Old Hwy 80 (SC 1883) Segment: Ribbonwood Road to Imperial County Line Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes)	 Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification. Minimize cost – No need to expand road to its build out capacity Community Consensus – Staff recommendation is equivalent to community's preference.
6E	Old Hwy 80 (SC 1883) Segment: Jacumba St to Laguna St Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2A Light Collector with Raised Median (2+ lanes)	 Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification. Build Community Consensus – The community would like to develop a town like atmosphere, staff recommendation is equivalent to community's preference. Support Land Use Goal- Neighborhood commercial use will be supported by proposed road classification.

Matrix: Mountain Empire-5 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
7	Cameron Road (SA 250) Segment: Entire segment Existing Condition: Unbuilt Current Classification: Rural Light Collector (2 lanes)	Delete CE Road	Minimize Costs – Roadway not required for circulation as forecast
8	Oak Drive (SC 650) Segment: Entire segment Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes)	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.
9	Lake Morena Drive (SC 660) Segment: Entire segment Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes)	Equivalent Classification 2.2E Light Collector (2 lanes) Note: The mapped version of Lake Morena Drive does not show actual alignment, missing "S" curve.	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.
10	Cameron Truck Trail Segment: Buckman Springs Road to Old Highway 80 Existing Condition: Dirt Road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Identify as Fire Access Road on community plan	 Road Capacity – CE Road is not required Appropriate Road for Land Use – Fire Access Road offers secondary egress during fire emergencies.
11	La Posta Truck Trail (SC 630) Segment: Entire segment Existing Condition: Dirt Road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Identify as Fire Access Road on community plan	• See No. 10.

Matrix: Mountain Empire-6 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
12	North Campo Truck Trail (SC 640) Segment: Entire segment Existing Condition: Dirt Road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Identify as Fire Access Road on community plan	• See No. 10.
13A	La Posta Road (SC 620) Segment: Old Highway 80 to State Route 94 Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Downgrade Classification 2.2F Light Collector with Reduced Shoulder (2 lanes)	Road Capacity – This road segment will operate at an acceptable level of service with the proposed classification.
13B	La Posta Road (SC 620) Segment: State Route 94 to Shockey Truck Trail Existing Condition: Unbuilt road Current Classification: Rural Light Collector (2 lanes)	Delete CE Road	Minimize Costs – Unbuilt segment is not needed as other local roads provide more than adequate access and egress.
14A	SC 590 (Shockey Truck Trail) Segment: Intersection with State Route 94 to Boulevard CPA boundary Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Local Public Road	Minimize Costs – CE Road is not required; a local public road is sufficient to handle future traffic.

Matrix: Mountain Empire-7 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
14B	SC 590 (Tierra Del Sol) Segment: Boulevard CPA boundary to Tierra Del Sol Existing Condition: Dirt road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Local Public Road	Improve Connectivity – Local Public Road is recommended to maintain local public road connection with Tierra Del Sol/Shockey Truck Trail and neighboring community.
14C	SC 590 Segment: Tierra Del Sol to East of Boulevard CPA boundary Existing Condition: Unbuilt Current Classification: Rural Light Collector (2 lanes)	Delete CE Road	 Build Community Consensus – The community wants to remove road from CE Network and not use the corridor for public roads. Support Land Use Goal – Low intensity development in a low density land use designation. Note: Border patrol routes already in place
14D	SC 590 Segment: Jacumba CPA boundary to Old Highway 80 Existing Condition: Unbuilt Current Classification: Rural Light Collector (2 lanes)	Delete CE Road	• See 14C.
15	Tierra Del Sol (SC 610) Segment: Old Highway 80 to SC 590 Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Downgrade Classification Local Public Road	Minimize Costs – Low traffic volumes do not justify a CE road.

Matrix: Mountain Empire-8 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
16	Live Oak Spring Road (SA 240) Segment: Entire segment Existing Condition: dirt road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network	Build Community Consensus – Community wants to delete dirt road from CE network as it traverses through private properties.
17A	Ribbonwood Road (SA 210) Segment: Intersection with Interstate 8 ramp to Lost Valley Road Existing Condition: 2 lanes, some dirt road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Local Public Road, Fire Access Road at the end of County maintained road to connect to Lost Valley Road	 Support Land Use Goal – Dead End Road with Low intensity development. Improve Connectivity- Fire access road needed to maintain connectivity and provide secondary egress.
17B	Ribbonwood Road (SC600) Segment: Old Highway 80 to Interstate 8 ramp Existing Condition: 2 lanes Current Classification: Rural Light Collector (2 lanes)	Minor Upgrade 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) CPG Preference: Equivalent Classification 2.2E Light Collector (2 lanes)	 Road Capacity – Minor upgrade needed for road to operate at LOS A -D; need intersection upgrade only. Note: Minor disagreement; congestion was not identified during community review.
18	Mc Cain Valley Road (SC 580) Segment: Old Highway 80 to Lost Valley Road Existing Condition: 2 lanes, some dirt road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Local public Road, Fire Access Road at the end of County maintained road to connect to Lost Valley Road	 Minimize Cost – CE road is not needed in this location because of low-intensity use. Improve Connectivity – Fire access road needed to maintain connectivity and provide secondary egress.

Matrix: Mountain Empire-9 November 7, 2006

	CE Road Segment	Board-Endorsed Network	Rationale
19	Jewel Valley Road Segment: Old Highway 80 to SC 590 Existing Condition: 2 lanes, some dirt road Current Classification: Rural Light Collector (2 lanes)	Remove from CE Network Local Public Road up to end of County maintained road	• See No.18.
20	Carrizo Gorge Road Segment: Entire Length Existing Condition: 2 lanes, some dirt road Current Classification: Collector Road (4 lanes)	Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes)	 Road Capacity – Road will operate at LOS A-C. Build Community Consensus – Community wants to see a wide enough R.O.W. maintained to accommodate future traffic associated with new border crossing.

Matrix: Mountain Empire-10 November 7, 2006